

**CORNWALL HISTORIC CHURCHES TRUST  
GRANTS MADE MARCH 2007 TO JUNE 2019**

The 229 Grants, totalling £820,657, were made with Cornwall Historic Churches Trust funds, funds provided to the Cornwall Historic Churches Trust by His Royal Highness The Prince of Wales Duke of Cornwall and The Cornwall Heritage Trust, and Partnership Grants made by the National Churches Trust on the Recommendation of the Cornwall Historic Churches Trust

<b>Date of Grant</b>	<b>Name of Church</b>	<b>Work</b>	<b>Grant Total</b>
03 June 2019	Carbis Bay Methodist Church	Repairs to Tower (Fast Track Maintenance)	£900
03 June 2019	St Sampson, Golant	Repairs to Rainwater Goods (Fast Track Maintenance)	£1,000
03 June 2019	St Sithney, Sithney	Replacement of floor and associated archaeological work	£5,000
03 June 2019	Our Lady of the Sea & St Anthony, St Mawes	Replacement of stained glass window	£150
03 June 2019	Old Kea	Repairs to four pillars, supporting valley roof, replacement of stonework	£2,000
14 March 2019	Truro Methodist Church	Repairs to ceiling and plaster bosses	£1,000
14 March 2019	St Julitta, Lanteglos	Replacement of rotten medieval timbers	£5,000
14 March 2019	St Mary's Sheviock	Overhaul of bell fittings, repainting of metalwork and treatment of floors. Replacement of bell ropes	£5,000
14 March 2019	Penryn Methodist Church	Roof Repairs	£600
14 March 2019	St Mary the Virgin, Bradoc	Installation of LED lights	£500
14 March 2019	St George the Martyr, Nanpean	Repairs to ensure building is safe & watertight, especially nave ceiling and roof above. Repairs to chimney and rainwater goods.	£1,800
14 March 2019	Falmouth Methodist Church	Essential Fire Prevention Upgrade	£2,000
14 March 2019	Fowey Parish Church	Renew all slates on North Aisle and replace rotten timbers	£3,400
14 March 2019	Truro RC, Our Lady of the Portal and St Piran	Flat roof needs replacement	£1,400

14 March 2019	Antony, St James The Great	Repair & Restore two Willimott windows	£1,500
09 October 2018	Calstock, St Andrew's Church	Bells.	£2,500
09 October 2018	Landulph	<ul style="list-style-type: none"> <li>• Replace the lead roof to the tower, and small access tower to the roof, and the perimeter lead gutter.</li> <li>• Repair cracks in parapet stonework and roof access tower.</li> <li>• Renew door to the access tower.</li> <li>• Remove perimeter flashings and renew</li> <li>• Renew the sarking boarding beneath the lead and replace any rotting timbers.</li> <li>• Provide a tower hoist to get materials up and down from the roof.</li> <li>• Provide temporary safety railing around the perimeter parapet.</li> <li>• Repair/replace cast iron rainwater pipe at North end of tower.</li> </ul>	£5,500
09 October 2018	Lelant, St Uny	<p>Serious problems with the floor, part of which is already unusable. So far, we have raised approximately two thirds of the £ 141,000 (plus VAT) needed for this urgent work. We have already raised money for, and repaired, the tower. The bell frame is being repaired this autumn but funds received for this would enable us to progress our money raising for the floor being repaired this autumn.</p> <p>(Also we have no disabled access nor internal toilets, and no facilities that could be uses by the wider community. The associated charities with whom you co-operate may be willing to give a grant towards our plans to install these.)</p>	£5,000
09 October 2018	Withiel. St Clements	Maintenance Grant	£1,000
25 June 2018	Zennor	<p>Due to corrosion over the last 90 years, the bell frame is in a dangerous condition and the bells can no longer be rung. The bells need some restorative work.</p> <p>Bell frame and bells to be removed from the tower.</p> <p>Bell frame to be rebuilt.</p> <p>Bell fittings to be restored and old timber fittings replaced.</p> <p>Bell wheels to be refurbished.</p> <p>Bells to be re-tuned.</p>	£7,500

25 June 2018	St. Michael's Perranporth	Our objective with this project is to upgrade our seriously outdated heating system. The current electric heaters are over 40 years old and are now in need of removal, replacement with a more efficient up to date heating system. The PCC has decided that an under floor system would greatly improve our carbon footprint and at the same time help us to reduce our energy costs	£1,000
25 June 2018	North Petherwin, St Paternus	For viewing work, cut out corroded Polyphant stone, make and re-fit with N H L 3.5 and coarse sand. Mortar to be analysed by the Cornish Lime Company. To drill and fit Cin Tec sock anchors to arch 24 number, 12 each side to a depth of 850 and 1,200 mm.	£500
25 June 2018	St Just-in-Penwith Parish Church	The roof was thought to have last been fully replaced in 1866 when the original waggon style roof was replaced with new Deal timbers and slates. We are looking to: Complete re-roofing of the church utilising Cornish slates Re-leading main valleys to ensure compliance with current guidelines and best practice. Carpentry works and repairs related to the above using traditional techniques, materials and methods Ceiling repairs using lath and lime plaster Masonry repairs to strengthen wall heads etc. Overhauling rainwater goods and low level drainage to ensure water is able to be taken effectively from the main body of the church. Removal of defective and unsafe chimney which is leaning heavily and in need of urgent attention and repair. Re-pointing works to remove defective pointing and inappropriate cement based mortars.	£13,500
25 June 2018	St Ewe	1. Urgent work to cure dampness in Spire by removing cement based mortar and re-pointing with Lime. 2. To address structural weakness in Spire resulting from Bell Frame main supports corroding	£13,500
25 June 2018	Blisland, St Protus and St Hyacinth	The vestry is an add-on in the 17th century we believe. The doorway is some three feet deep. The supporting beams have rotted through due to the pointing of the outer wall and doorway having been eroded due to weather. We need to replace like with like wooden beams and re-plaster internally and re-point outside. We also need to repair the door to the vestry.	£2,000

23 March 2018	Zion Community Church,	<ol style="list-style-type: none"> <li>1. Improving the fire safety of our facilities, in accordance with the actions of a Rand Survey conducted in 2015.</li> <li>2. Improving our presence in the town through necessary maintenance.</li> <li>3. Making our facilities more disabled and family friendly.</li> </ol>	£2,100
23 March 2018	Warleggan, St.Bartholomew's	The restoration of the tower and bell chamber including lifting the lead, the renewal of roof and floor timbers,the rebuilding and strengthening of parapets and the replacement of broken downpipes.The tower will be repointed with lime mortar ( all cement pointing and interior cement wash to be removed).	£2,000
23 March 2018	Warbstow, St Werburgh's	To remove and have repaired the vestry window and the central window on the north side of the church, both of which are in a very poor state.	£2,500
23 March 2018	Sheviock, St Mary's	Approximately 95% of the joints in the tower and spire are loose or hollow and the tower and spire is now listed on the English Heritage At Risk register. There has been a very recent fall of timber within the tower and signs of increasing water penetration which drive an urgent need to safely remove the two bells. Works will include the installation of a safe means of access to the bells so that they and the bell paraphernalia can be inspected, repaired and maintained in the future. The plaster ceiling in the nave was identified as Priority A in the 2013 Quinquennial Report and has subsequently been netted. The Quinquennial inspection of April 2017 also recommended the need to survey and repair the roof bosses during the repairs to the plaster ceiling.	£4,000
23 March 2018	Perranporth Methodist Church,	Removing cement mortar strap pointing form roadside face of church building and replacing with flush lime mortar.	£1,300
23 March 2018	Penzance RC	Within a development of the crypt levels of the church to give us parish & community facilities to include kitchen, toilets and disabled access (separate funding mostly in place), we are also needing to carry out repairs at crypt level to lintels and stone work to support the church above. This is obviously necessary (rather than desirable) work and is rather urgent & requires completion within the same time period as the separately funded facilities development work detailed above	£6,500

23 March 2018	Lanhydrock, St.Hydroc	In recent years Quinquennial Inspection reports have identified problems of damage due to water ingress , arising from deterioration of roof leadwork and slate roofs , and both high and low level drainage, uch that the church structure is no longer fully weatherproof , and in need of increasingly urgent repair. A project has been prepared , which will comprise:- a) replacement of two large leadwork valleys in the roof , and associated overflows b) repair of slate roofs c) replacement of leaking cast iron guttering d) refurbishment of low level drainage e) making good water damage to the interior of the church	£7,500
23 March 2018	Gwennap, St. Wenappa	2015: Plaster on the internal southwest wall was stripped to allow the wall to dry out. External repointing in lime mortar- replacing old cement work - was carried out at that time. The internal wall is now dry adeady for re-plastering in lime.	£2,500
11 October 2017	Breage, St Breaca Church,	Tower Work. Accessing the pinnacles with scaffolding, removing defective pinning and fixings, dissembling the same, re-securing, pinning, bedding and pointing upon completion. Whilst scaffolding is erected, high level pointing will be undertaken to the	£5,000
11 October 2017	Camborne Wesley Methodist Church	Murray is teasing out eligible work from an application that was largely ineligable. Likely to be security doors and health and safty issues.	£4,500
11 October 2017	Cawsand Congregational Church	For Adjustment	£500
11 October 2017	Lanhydrock, St.Hydroc	a) replacement of two large leadwork valleys in the roof , and associated overflows b) repair of slate roofs c) replacement of leaking cast iron guttering d) refurbishment of low level drainage e) making good water damage to the interior of the church	£4,500
11 October 2017	Linkinhorne, St Melor's	Restoration work on two paintings as set out in Grant Application	
11 October 2017	Portscatho United Church	Various works to Porch	£1,850

11 October 2017	Quethiock, St Hugh	Two windows on the North wall have suffered movement due to failure of metalwork at their base .The glass will be removed and mullions hydraulically returned to the correct position, before making good and replacing the glass. The windows are part of the	£3,000
11 October 2017	Veryan	Retrospective application for weather proofing the Tower following storm damage. The Clock was covered by insurance, but the "making good" was not. The actual cost exceeded the estimate.	£3,000
11 October 2017	Wendron, St Wendrona	Repair work to roof areas including: Renewal of north and south facing slopes Minor repairs to central slopes Repair to porch roof Repair to tower roof also joinery and flooring repairs caused by damp Improve rainwater disposal system	£5,000
28 June 2017	Botus Fleming, St Mary's	Replace lead valley and renail/replace both inner valley roof pitches	£6,500
28 June 2017	Charlestown, St Paul's Church,	Works to the south façade of the Church: replacement of the roof slates to the Nave, South Transept and Chancel and associated leadwork; replacement of rusted iron ferramenta and security grilles to the clerestory windows, aisle windows and transept windo	£4,000
28 June 2017	Grampound, St Nuns	Removal of the inside plaster of the building due to inappropriate materials being used The Belcote requires pointing in order to stop water migrating into the West wall of the building Part of the present flooring requires taking up due to rot, and the	£2,000
28 June 2017	St Just Free Church	To main Church building: Remove all existing life-expired slates and replace with new wet-laid; Repair or replace rotten or damaged roof-level timbers, including guttering supports, bargeboards etc. as needful Remove all existing rainwater goods and repla	£2,000
28 June 2017	Liskeard, St. Martin's	The gas fired blown hot air heating system has failed totally and cannot be repaired.We have been advised that the most suitable replacement that is permissible, for a church of this size, is underfloor heating. This will involve substantial reordering	£3,650

28 June 2017	Par	To undertake major masonry repairs, internal timber repairs and improvements of floors and other elements to the crumbling spire and tower; conserving the tower and spire for future generations.	£4,300
28 June 2017	Stratton Methodist Church	The gas boiler is 13 years old and leaks; it has failed to operate on several occasions this last winter. The radiators do not extend into the organ area nor the area beyond the Communion Rail, including the pulpit. The boiler is inconveniently housed u	£1,250
22 March 2017	St Uny	The architect has identified serious problems with the floor, part of which is already unusable. So far, we have raised £ 90,000 of the £ 141,000 (plus VAT) needed. Our latest quinquennial inspection took place in September 2016 and confirms the urgency o	£500
22 March 2017	Cawsand Congregational Church	Guttering and downpipe replacement needed on one side of the church. Also treatment for woodworm damage, not yet serious, but preventative measures needed, especially in roof timbers.  This is a re-application after further work has been revealed by a QI.	£3,500
22 March 2017	St Winwaloe Church, Tremaine	Repairs required on the church were identified in a Quinquennial Church Inspection Report prepared on the 18th June 2014, including: filling open joints in stonework on the church tower and walls; repairing pointing to tower pinnacles; repairing split lea	£6,000
22 March 2017	St John the Evangelist, Treslothan	Roof repair and maintenance works as recommended within the most recent quinquennial survey report. Works will involve the stripping and re-slating of the Chancel and Lady Chapel roofs, which are heavily dilapidated, along with maintenance repairs to slip	£8,000
22 March 2017	Lanner, Christ Church	Replace Roof	£8,000
22 March 2017	Jacobstow, St James	Restore two altar oil paintings	£1,000
13 October 2016	St Veep Parish Church	Tower and Bells	£10,000
13 October 2016	Sancreed, St Creden	Roof	£12,500
13 October 2016	Quethiock, St Hugh	Internal Roof Slats	£3,000

13 October 2016	Mullion, St Mellanus	Plaster	£2,000
13 October 2016	Lanteglos-by-Camelford, St. Julitta.	Roof	£12,000
13 October 2016	Laneast	Medieval Windows	£14,500
13 October 2016	Gunwen Methodist Church	Roof	£5,000
13 October 2016	Devoran St John and St Petroc	Tower and Gables	£3,500
22 June 2016	St Winnow Parish Church	Tower	£5,000
22 June 2016	Temple	Roof	£15,000
22 June 2016	Parish Church of St. Dominica & St. Dominic, St. Dominick	Plaster and Tiling	£2,000
23 March 2016	Truro Cathedral	Major Roof Works	£5,000
23 March 2016	Perranporth Methodist Church	Clean and Overhaul Chapel Organ	£500
23 March 2016	Penryn Methodist Church	Water damage to Gutter Boxes, Flooring and inside stairwells.	£1,200
23 March 2016	Penryn Highway Community Church Centre	Windows and Lighting	£1,000
23 March 2016	St. Mawgan in Meneage	Extensive roof and other works.	£5,000
23 March 2016	St Gorran Church	Tower	£2,500
23 March 2016	Guval Parish Church	Roof	£3,200



23 March 2016	St Cubert	Roof and rainwater goods	£5,000
23 March 2016	Cawsand Congregational Church	Rainwater goods and woodworm	£2,500
07 October 2015	Zennor	<ol style="list-style-type: none"> <li>1. Remove the pews from the side-chapel and store</li> <li>2. Remove the t&amp;g timber platform around the altar and store.</li> <li>3. Dig out and repoint internal walls with a lime sand mortar</li> <li>4. Repair the wood block floor and treat with preservative.</li> <li>5. Reposition the</li> </ol>	£5,400
07 October 2015	Redruth, St Euny	The repair work to be carried out is to the lychgate which has unfortunately fallen into disrepair because it has previously been cement rendered, It needs to be lime rendered in the traditional manner.	£3,275
07 October 2015	Quethiock, St Hugh's	The report from our surveyor highlights that the nails holding the roof slates in place have nail sickness and are failing. Since the report we have had over 20 slates slip. The leaking roof risks the coloured wagon roof ceiling as well as damaging the int	£9,700
07 October 2015	Paul	Entire memorial window frame will be removed, replicated in Forest of Dean stone and replaced; the glass will all be removed, cleaned, re-leaded and re-fitted into the new framework.	£9,250
07 October 2015	Truro, St Clement,	<p>Complete re-roofing</p> <ul style="list-style-type: none"> <li>-Roof structure repairs</li> <li>-Replacement of lead valleys</li> <li>-Repointing</li> <li>-Overhaul rainwater goods and improve low level drainage</li> <li>-Repairs to ceiling</li> </ul>	£3,950
07 October 2015	Tintagel	<p>Remove slate slabs from east of screen</p> <p>Remove tiles from the west of screen</p> <p>Carefully remove soil from each side of the sill avoiding as much loss of decayed material as possible.</p> <p>Have archaeologist inspect/examine soil around and under sill</p> <p>Introduc</p>	£8,300
07 October 2015	Sennen	Organ Restoration	£2,550

22 June 2015	St Goran	We want to open up the 13th century doorway in the north wall of the church and provide a new access to the doorway. This will provide a much needed disabled access to the church and also help to solve the damp problems at the west end of the church. This	
22 June 2015	Pillaton and St Mellion	This is a request for a follow-on grant for re-pointing the outside walls of both churches to replace failed inappropriate cement based pointing. This is to augment the work being carried out inside the church at Pillaton.	£2,000
22 June 2015	Lelant, St Uny	Floor has to be replaced and at the same time it was decided that we would take the opportunity of place the heating system under the new floor in the interest of efficiency.	£4,500
22 June 2015	Altarnun, St Nonna	Replacement of existing (failing) organ with better second-hand instrument. Replacement organ already purchased and stored (disassembled) in St.Nonna's.	£5,000
22 June 2015	St Neot	The church Tower is leaking and damaging the interior including the frames of two windows. We need to replace some masonry and completely repoint the Tower. The church has been placed on the English Heritage 'At Risk' Register.	£5,000
22 June 2015	St Ewe	Repair and replace missing roof slates: Provide replacement lead flashing to main roof valley Rake out cracks in vestry chimney stack and replace in lime mortar	£3,000
22 June 2015	Boconnoc Church	Re-lead parapet to south; Re-lead north parapet/valley; Patch repair or re-lead central valley Re-slate where lead attended to Point open joints and lead to coping stones Re-set and point southern parapet stones on lead Renovate other aspects of guttering	£3,000
20 March 2015	St.Piran & St. Michael, Perranuthnoe	Details about the repair work: Remediation of damp issues to Church walls; 1) Remove internal plaster and replace with bag rub lime pointing. 2) Rake out and repoint external walk with lime momr. 3) Improve external surface water drainage. 4) Overhaul rai	£9,100

20 March 2015	St Stephens-by-Saltash	The tower has suffered ingress of water going back to 1934. With the heavy rain and wind of last winter the repair has become more urgent before further damage takes place. A complete rope survey of the tower by an architect and builder has been completed	£3,000
20 March 2015	St John the Baptist and St John-in Cornwall, Torpoint	To replace the ceiling in the Nave and Chancel. To remove and replace the tiles and underlying screed in the Chancel	£6,500
08 October 2014	St Just Free Church	To main Church building: Remove all existing life-expired slates and replace with new wet-laid; Repair or replace rotten or damaged roof-level timbers, including guttering supports, bargeboards etc. as needful Remove all existing rainwater goods and repla	£3,000
08 October 2014	Polperro Methodist Church	A recent quinquennial advised that important electrical work needed to be done to improve safety. Also signs of active woodworm were detected so a survey was recommended [and has now been made]. Last winter the heating broke down. The present control sy	£2,000
08 October 2014	St Keyne	The repairs are necessary following a lightning strike on the church tower, causing one pinnacle to fall damaging the church tower roof and main the church roof in various places, before landing in the nave roof valley as well as destroying the electrical	£3,500
08 October 2014	Riverside United Church	2010 quinquennial noted that roof may need replacing soon. Major problems with water ingress over last 12 months. We decided patching/repair would not be cost effective as this would only delay need for new roof. So Phase 1 is to put on a new slate roof.	£7,000
08 October 2014	St Mawgan in Meneage	Rewire Church, new distribution board, replace lights Refurbish Porch gate and decorative ironwork Refurbish Front gate arch and lantern Rebuild stub wall by South Gate Repair South Gate	£3,000
08 October 2014	Launceston, St Mary Magdalene	The church is a three aisle building with central nave, north & south aisles and chancel comprising Choir & Sanctuary. The aisles are separated by granite columns supporting a slightly pointed wagon roof with carved angels ranged along the wall plate, bar	£4,000

30 May 2014	St. Stephen – in - Brannel	Roof slating & Lead & Dry Rot repairs	£5,000
30 May 2014	Pillaton Church	The church was hit by lightning in January 2013 resulting in over £300,000 repair bill. The church reopened for Remembrance Day service with the church full and the bells ringing again. This was mainly covered by EIG insurance but £16,000 of non-insurance	£2,500
30 May 2014	Penzance Catholic Church	Replace rotten basement windows	£1,850
30 May 2014	St Hugh's, Quethiock	The lead in the gully between the North aisle roof and the Nave roof has failed . The rain leaks in and is collected in buckets. We are going to replace the lead, woodwork and failed slates. The sounding Chamber floor is rotting,(leaks from the tower ro	£4,600
30 May 2014	Paul Church	<ul style="list-style-type: none"> <li>• Wooden frame of Georgian glass window at the east end of the church is badly rotted in places and in need of repair.</li> <li>• A large piece of stone has fallen from the window surround in the tower and other areas of stone in the vicinity are unstable.</li> <li>• Two s</li> </ul>	£3,500
30 May 2014	Stoke Climsland Parish Church	To remove all cementitious pointing and repoint with a lime mortar of an appropriate strength and colour. Where necessary, grind out slate joints to sufficient depth to allow sound repointing in lime mortar. South Elevation - Belfry Stage and Parapet Sout	£3,200
30 May 2014	St Tudy	Removal of pews at the rear of the Church and replace cleared area with Delabole slate: Lay under-floor heating units beneath the cleared area of the rear of the Church. Fitting of under-seat heating throughout the rest of the Church including Chancel Pew	£3,000
08 March 2014	St Nicholas Church, Tresco	Restore the roof, external repointing and replastering of the south elevation together with internal repairs.	£3,500
08 March 2014	St Joseph's Catholic Church, Hayle	Scaffold, rainwater goods, windows and exterior painting.	£2,500
08 March 2014	Gwennap	Re-roof the exterior north and south slopes of the church, and the gables over the porches	£5,000

08 March 2014	St. Dominic	The existing slate coverings on the Church roof are showing considerable distress, particularly on the north slope of the north aisle. A recent professional inspection of the north aisle roof indicated that slates are continuing to become loose or have mo	£3,000
08 March 2014	Veryan, St Symphorian	Replacement of 100yr old pumped radiator system that is beyond economic repair with a network of under pew heaters in order to provide localised warmth and four fan assisted storage heaters to provide background warmth and to sustain the fabric of the Chu	£4,000
08 March 2014	Ladock	Replastering of the south internal wall and decorating the church with lime wash (eligible part of larger ineligible kitchenette scheme)	£3,500
09 October 2013	Cury, St Coarentyn	Raking out and re-pointing with lime mortar all faces of the Tower	£3,000
09 October 2013	Mevagissey, St Peter's	Painting and decorating interior of church. Scraping away loose and peeling paintwork. Treating all areas showing signs of mould and mildew with de-fungicide. Filling, sanding and smoothing where necessary. Applying two coats of emulsion throughout. This	£2,000
09 October 2013	St Austell Friends Meeting House	The project is to complete urgent high level repair and maintenance work as identified by the Quinquennial inspection in 2012. This highlighted repairs to roof slates, the ridge and hips, replacement of the fascia to all elevations, repairs to wallplates,	£2,500
09 October 2013	Newquay Christian Centre	The heating system was presumably installed in the church when constructed (it is a wet system) with old narrow bore boiler pipe giving the radiation and a few radiators hung in various places. The system is not only antiquated, but it is also non enviorm	£2,000
09 October 2013	Truro, St. George the Martyr	1. Repairs to tower floor & improve access 2. Repairs to both transept gables – slipped coping stones 3. Overhaul of rainwater goods at high and low levels	£3,000
28 May 2013	The Sacred Heart and St Ives	To remove 12 diamond pattern windows To completely restore all windows using existing glass and replacing broken panes with glass to match as near as possible. To remove existing hoppers and replace windows as required To re-fix all panels to openings an	£2,500
28 May 2013	St Austell Baptist Church	Over the years a number of roof slates have had to be replaced as the nails securing slates have corroded and failed, causing some slates to fall. Replacing the entire roof has now become, not only a matter of safety but also one of econom~cn ecessity as	£3,500

28 May 2013	Innis Chapel	Chapel roof and porch in urgent need of a complete re-slate to modern standards.	£3,000
28 May 2013	The Collegiate Church of St Endellion	Extensive urgent repair work is required to the roof The South slope of the North Aisle requires re-slating The North slope of the Nave Roof must be re-slatted The North Valley Gutter needs renewing and widening Defective haunching and pointing to gable pa	£5,000
28 May 2013	Lezant Church	Repair of roof slopes and reslating as necessary with rag slates. Repair of two valley gutters and overhaul of rainwater goods.	£4,500
20 March 2013	St Piran & St Michael's Church, Perranuthnoe	Restoration of East Window, modification of lighting in the nave, upgrading of electrical works to meet modern standards, further restoration of the West Door , and renewal of storage space in the Tower area for vestments and Church effects. In addition w	£3,000
20 March 2013	St Michael Caerhays	Repair and restore two Willimott windows (north transept and south aisle), repair stonework as necessary. The work on the stained glass will be carried out by Susan Ashworth (stained glass artist and conservator).	£4,000
09 October 2012	Camelford Methodist Church	Re-roofing (and installation of disabled toilet & fire escape which is not the subject of a grant application but included in the project cost)	£2,500
09 October 2012	St Mawgan-in-Meneage	The central heating boiler is irreparable. The boiler room roof is collapsing and will need to be replaced before a new boiler is installed. We are also advised that the old pipe work should be taken out and replaced with radiators.  Due to the urgency	£3,500
09 October 2012	St Michael Caerhays	Repair and restore 2 Willimott windows (north transept and south aisle), repair stonework as necessary. The work on the stained glass will be carried out by Susan Ashworth (stained glass artist and conservator).	£5,000
09 October 2012	Truro, St John	Restoration of the 'Resurrection' apse mural	£2,000
09 October 2012	Probus, St Probus and St Grace	Window 3: To replace missing stained glass pieces, re-lead and removal of existing ferrous ferramenta with brass bar. Deal with Cills and traps. Repair /replace damaged stonework. Window 4: Add new exterior grill, re-lead window as necessary and remov	£2,000

09 October 2012	Flushing, St Peter's	Rainwater goods, rendering. Repair to external wall rendering, particularly coloured mortar to mouldings round window openings and gable parapet mouldings	£2,082
09 October 2012	Gunwalloe, St Winwalloe	Phase One Hack off all interior plaster Consolidate walls as necessary Mortar and bed rake out joints Phase Two Bag rub plaster after walls have settled Lime wash interior walls  NCT (through CHCT) Gave £2,500 for Phase One, This application for Phase two	£3,500
09 October 2012	Ruanlanihorne, St Rumon's,	The Quinquennial report of 2008 noted that major conservation work to the church windows was needed. In May 2011 a report was commissioned from Alan Endacott of Angel Stained Glass, Lewannick. The report noted that nine of the twelve windows required re-l	£3,000
12 June 2012	St. Keverne Parish Church	The existing wiring is aged and worn and must be replaced and it for this we would appreciate your help. The development plan and faculty permission includes a complete re-wire of the entire building, as appropriate, to support the proposed lighting, soun	£2,500
12 June 2012	St Buryan	St Buryan were awarded a grant of £6k (£3k CHCT + £3K Manifold) in Oct 2011. They have asked us to reconsider the grant in the light of an increase in costs from £261K to £359K with no increase in the EH grant. Details in the letter dated in the grants	£4,000
12 June 2012	Duloe, St Cuby	Conserve the tombs and slate memorials in the Colshull chapel.	£4,000
12 June 2012	St Enoher	The project is to complete urgent high level repair and maintenance work as identified by the Quinquennial inspection in 2010, which highlighted the work as being top priority. The work will include re-roofing all but a small portion of the church	£5,000
12 June 2012	Dobwalls United Church	The external stone walls of the Chapel building, which at the moment are painted grey and causing a problem with damp, will be stripped back to the stone work and treated, therefore making the exterior of the whole of the building the same. We will then	£2,500
24 March 2012	Wadebridge Christian Centre	Repairs to the roof which is constructed of Delabole rag slates, which are worn and thin. The roof needs a full overhaul - felting, battening and replacing of worn roof slates, with new fasclas and guttering.	£1,000

23 March 2012	Tresmere, St Nicholas	Floor and Pew Repairs Rainwater Goods Window Repairs	£4,000
22 March 2012	Manaccan  CHCT Grant includes £3,000 from Manifold Trust	Roof Repairs. Fix sacrificial lead on both sides of gully. Replace plastic guttering with cast iron plus down pipes Prime undercoat and gloss. Clean out tower debris, clean moss etc. from roof and repair broken and damaged slates. Belfry Door. (at pre	£6,000
21 March 2012	Mevagissey, St Peter's	Rainwater goods. Cleaning, Painting, replace brackets	£950
12 October 2011	St John the Baptist, Pendeen	Hack off all interior plaster Consolidate walls as necessary Mortar and bed rake out joints	£2,500
12 October 2011	St Buryan  CHCT Grant includes £3,000 from Manifold Trust	The work is essentially high level repairs to the roof and valley guttering. Both valleys over the arcades need re-leading; all six slopes of the roof require re-slating; guttering and downpipes need refurbishing; several rotten roof timbers need replacin	£6,000
12 October 2011	Davidstow, St David	Major repairs to tower masonry, roof, floors and belfry. Also replace bell frame.	£5,000
12 October 2011	St Levan	1. Under drawing of ceilings with Glasroc boarding to internal plaster 2. Internal plaster patching, lime washing and internal decorations 3. Work to the main roof, where there is ingress of water against the tower.	£2,500
12 October 2011	St Just In Roseland	Complete roof restoration. Overhaul and repainting all rainwater goods. Cut out defective pointing of the upper tower masonry and renewal with lime mortar. Repairs to the north belfry opening following detailed inspection. All the above work to be carrie	£5,000
12 October 2011	Boconnoc Church	Re-slate Roof	£2,500



12 October 2011	St Winwalloe, Gunwalloe	Hack off all interior plaster Consolidate walls as necessary Mortar and bed rake out joints	£2,500
13 June 2011	Tuckingmill, All Saints	This church dates back to 1845 and was built by the Bassett family. Existing external Stone-work is of red sandstone, with granite window and door surrounds, string courses, plinth and pilasters. Over the years the sandstone has eroded and water penetrati	£2,500
13 June 2011	Maryfield Church, Torpoint	There is a need to repoint all faces of the spire using a lime based mortar. At the apex of the spire there is a slate cap supported by iron bars which are corroded to such an extent that the slate cap is unsafe and needs replacing. One bell louvre is mis	£2,000
30 March 2011	Cury, St Corentyn	Re-Wire and re-visit of application of 10 03 25 for Replacement of bell support framework. Total removal of the bell installation Including bells and all other components. Severe corrosion of main and secondary RSJ's.	£2,500
30 March 2011	St Stythians, Stithians	Roof and Tower. Subject of English Heritage Grant	£4,000
30 March 2011	St Issey	Two reinforced concrete ring beams were installed during the 1950's to strengthen the tower's stonework. Major corrosion has taken place since, making it dangerous to ring the six bells, and threatening the security of the tower. 1950's repairs must be re	£2,500
30 March 2011	Landulph, St Leonard & St Dilpe	The important 17th Centurycarved wooden panelling, which used to be pew ends and were put on the back wall when the pews were renewed at the beginning of the 20th century, need repairing as they have become very damp and (some are rotting) against the wa	£2,000
30 March 2011	Beacon Methodist Church	Deterioration of the stonework mainly due to frost damage	£2,500
30 March 2011	St Dominic	(a) Replacement of heating boiler, replacement and extension of the heating system; (b) Erection of a glass Tower Screen; and (c) Creation of a Family Area.	£2,000
30 March 2011	Jacobstow, St James's	Roof: Valley and Tower	£4,000

30 March 2011	Penzance, St Mary's	One of the beams which supports the gallery on the S.W. side of the church has started to rot where it is exposed to the full force of the prevailing and very wet, southwest wind. The church surveyor has decided that the end of this beam and the other two	£2,500
30 March 2011	St Paternus Church, North Petherwin	Weld/repair bell no. 2 which is cracked, thus disabling the quarter chimes of the clock. Repair & refurbishment of the fixtures & fittings of all the six bells in the ring. These have come to the end of their useful life, and they will soon become unsafe	£1,000
30 March 2011	Bodmin, St Petroc	Complete new lighting scheme new sound system: moving of Font to a more theological position together with cleaning to also give it space and dignity.	£2,500
14 October 2010	St Morvetha, Morvah  Includes £5,000 from the Manifold Trust	The lead to the tower roof needs to be replaced. Remedial works to the nave walls which have displaced possibly due to roof structure movement. Slate roof to the north side needs replacing. Currently there is water penetration to the tower and roof which	£6,000
14 October 2010	St Juliot, Boscastle	Tower Weather proofing Replace cracked Quoins	£2,000
14 October 2010	Helston, St Michael	Re-roof	£5,000
14 October 2010	Lizard Methodist Church	Enhancements to the heating system	£250
14 October 2010	St Illogan Church  Includes £5,000 from the Manifold Trust	Re-roof	£10,000
14 October 2010	Roche, St Gomonda	Roof	£3,500
14 October 2010	Penwerris Includes £5,000 from the Manifold Trust	Re-roof	£10,000

14 October 2010	Boconnoc Church	Work to replace a heating system and to improve Boconnoc's suitability as a community resource	£1,000
14 June 2010	St. Clether – The Parish Church of St. Clederus	To overhaul, restore and install a 2 Manual Hele Pipe Organ at the west end of north side. To remove three pews at the west end on north side. To run an electric cable extension from the electric socket on north wall of tower to new socket on north wall	£2,500
14 June 2010	Towednack Parish Church	Tower Roof: Lead Repairs	£500
14 June 2010	St Michael Caerhays	Restoration of first two of ten stained glass windows made and installed by Revd William Willimott [phase one of several]	£3,500
14 June 2010	Cubert, St Cubert	New North Door Repair to interior of Tower, Bell Frames and Bells Repair to War Memorial Repair to ceiling of S Transept	£4,000
14 June 2010	Carn Brea Village Methodist Church	Repointing and associated barge board repairs	£2,000
25 March 2010	Cury, St Corentyn	Replacement of bell support framework. Total removal of the bell installation including bells and all other components. Severe corrosion of main and secondary RSJ's.	£2,000
25 March 2010	Washaway, St. Conan's	Complete Reroofing	£2,000
25 March 2010	Rame, St Germanus	Nail sickness; Re-Roof EH Declined a grant - not urgent	£3,500
25 March 2010	Perranuthnoe, St Michael and St Pirran	The clock mechanism is supported on 2 RSJ beams. A recent survey highlighted corrosion in the wall and the recommendation by the Cumbria Clock Co Ltd that they be replaced. Further advise from an independent Structural Engineer suggested from a safety sta	£1,000

25 March 2010	Altarnun, St Nonna	Restoration of Bells and Bell-frame: Bells – quarter turn, new bearings Frame – two new framesides, galvanise whole frame, new supporting grillage. Fittings – new pulleys, stays, sliders, and running boards.	£2,000
25 March 2010	Redruth, St Andrew's	(a) replacement of central heating boiler and radiators in church (see business plan) (b) repointing of West Elevation of church which is currently letting in water	£3,000
25 March 2010	Newquay Christian Centre	The roof of the building has suffered nail rot for many years and has been getting progressively worse as the years have gone by. It is now at a stage where re-roofing is absolutely necessary, along with new lead work and guttering. Water ingress is stave	£2,500
25 March 2010	Shevioc, St Mary's	Repairs are required to the: South Transept The Main Church Body and extrnally	£2,500
25 March 2010	St Mellion, St Merlanus	Refurbishment of rainwater goods Re-pointing of Stonework Internal plastering	£4,000
25 March 2010	Morwenstow	Replacement of structurally critical main beam supporting tower roof, the existing beam having been severely weakened by rust and being beyond repair.	£2,000
13 October 2009	Truro Cathedral	Deterioration of the limestone components, which form the major part of the Victoria tower	£5,000
13 October 2009	Tregony Congregational Church Fore Street Tregony	Part replacement windows Heating System - replace electric convection with radiators run through from next door hall	£2,500
13 October 2009	St Martins and St Meriadoc Parish Church, Camborne	Replace tiled aisles, flooring, heating system, electrics and joinery	£5,000
13 October 2009	St Briochus, Lezant	Assorted work to Tower, Lead, Rainwater goods and pointing	£3,000

13 October 2009	Our Lady Of The Portal And St. Piran, Truro	Deteriorating lead work over the altar causing damage and disruption required immediate attention. New lead and associated wood and roof replacement needed.	£1,500
13 October 2009	St John's Church Truro	Roof and High level Repair	£2,500
13 October 2009	Parish Church of SS Probus and Grace, Probus	To repair and renovate stonework and stained/ plain glass in most of the church windows, including broken pieces (in stained glass windows) and panes (in plain glass windows.) The project is also to replaced corroding iron window ties with non-ferrous typ	£3,000
22 May 2009	Troon Methodist Church	Repair defective plaster and re-point	£2,500
22 May 2009	St Cuby's Duloe Includes £5,000 from the Manifold Trust	Restore roof and rainwater goods	£10,000
22 May 2009	Mullion Methodist Church	Clean, and repair three stained glass windows	£1,500
22 May 2009	St Pol-de-Leon, Paul, Penzance	Window restoration project	£4,000
22 May 2009	St Newlyna, St Newlyn East	Lead, timber and rainwater goods repairs	£5,000
22 May 2009	Fowey Parish Church	Restore main roof	£4,000
22 May 2009	Come to Good Meeting House Includes £5,000 from the Manifold Trust	The project concentrates on high level roofing repair and maintenance to the exterior fabric	£9,000
26 March 2009	St Endellion	Replacement of Lighting System	£1,000
16 October 2008	Zion Congregational Church, St Ives	Replacement of Church Hall Roof (used for occasional worship)	£2,800

16 October 2008	Gulval	Repair of bulges in retaining wall enclosing island containing church and graveyard	£1,500
16 October 2008	St John's Treslothan	Removal of dangerous masonry (Church is £8,000 in debt). Geoffrey will brief at the meeting	£350
16 October 2008	St Symphorian Veryan	Work on Windows (Joanna is visiting and will report to meeting)	£4,000
16 October 2008	St Sampson Golant Includes £1,000 from the Manifold Trust	Removal of cement pointing and replacement with lime mortar. Replace wall plates to bell chamber; replace floor in deadening chamber. Unseal window in chamber and replace with louvres.	£5,000
25 May 2008	St Winnow  Includes £4,000 from the Manifold Trust	Restoration of important stained glass window. Includes £4,000 extra-ordinary grant	£8,000
25 May 2008	St Stythians, Stithians	Re-slate north slope, repair southern lead valley	£4,000
25 May 2008	Lanner Methodist Church	New Roof Needed	£2,500
25 May 2008	St Blaise	Heating system: required to maintain good condition of recently restored roof	£1,000
25 May 2008	St Paternus, North Petherwin	Tower and parapet work	£2,500
06 March 2008	St Piran & St Michael's Church, Perranuthnoe.	Tower Restoration	£3,500
06 March 2008	St Eval	Rebuilding of Pinacles	£4,000
06 March 2008	Lostwithiel St Bartholomew	Work on Spire (Grant addiotional to £4,500 made in Sep 07)	£4,500
17 October 2007	St Mabyn	Restoration of church roof	£5,000
17 October 2007	St Austell, Holy Trinity	Replacement of lead gullies in north and south elevation. Lead flashing around tower and elsewhere.	£4,500

17 October 2007	Pillaton St Odulph	Window Stained glass repairs	£500
17 October 2007	St Dominick	Repairs to rainwater-goods	£500
17 October 2007	Penzance Chapel Street Methodist	Heating system repairs	£3,000
17 October 2007	St Mellion	Window Stained glass repairs	£500
17 October 2007	St Clement Withiel	Move of Wedlake organ to reveal Tudor east window with a small amount of Tudor stained glass (Crest of Prior Thomas Vyvyan)	£3,000
17 October 2007	Phillack St Felicitas and St Pail	Re-slating and leadwork. Complete rainwater-goods upgrade.	£4,000
17 October 2007	Lostwithiel St Bartholomew	Re-pointing spire	£4,500
15 May 2007	Newquay Reformed Baptist Church	Re-plaster the internal ceiling of our main church area.	£1,000
15 May 2007	Mullion Methodist Church:	Replacement of all downstairs windows	£400
15 May 2007	Redruth Methodist Church:	Organ repairs	£750
15 May 2007	St Mary's Roman Catholic Church Falmouth	Repair upper area of Bell Tower and install second finial for lightning protection.	£1,000
08 March 2007	St Stythians, Stithians	Renovation of Floor of raised west-end of Church, replacement of rotten joists and boards.	£3,000
08 March 2007	Gwithian Methodist:	Re-thatching following Thatch collapse. Walling repairs, lime-washing, some joinery work.	£2,800
08 March 2007	Falmouth, All Saints	Total renovation of East Window and surrounding stonework. Provide security screen	£4,000
08 March 2007	Friends Meeting House, Marazion	Disabled access and general repairs	£2,000